# Safe Operating Procedures

Make: Dynapac Model: CA1300PD

Type: Rollers, Padfoot Self Propelled

Serial Number: TKA025347



# Recommended PPE - Subject to Company & Site Policy



#### SOP Roller, Padfoot Self Propelled

#### **GENERAL & START UP**

Read and understand manufacturer's operational manual

Complete pre-operational checklist (never use faulty or defective machinery)

All operators must be free from the direct and after effects of drugs and alcohol

Never operate in a poorly ventilated area, carbon monoxide is colourless, odourless and poisonous

Ensure work area is clear of bystanders and hazards prior to starting engine and operating machine

Once engine is started confirm control pattern and machine function

Ensure that you are familiar with all attachments and the clearance distances between attachments and any other part of machine

! ALWAYS WEAR YOUR SEAT BELT

! NEVER USE PHONE WHILE OPERATING MACHINE

! NEVER CARRY PASSENGERS

Ensure work area is clear of all bystanders

Always consider ground type prior to travelling machine, use extreme caution on slippery surfaces such as metal, ice etc

Never travel across slopes, travel up and down slopes only

Refer to power line approach distance label re safety around power lines

### **ROLL OVER HAZARD**

! NEVER POSITION MACHINE OVER "SHELF" ADJACENT EXCAVATION

! NEVER POSITION MACHINE UNDER PRECIPICE OR OVERHEAD OBSTRUCTIONS

! ALWAYS USE EXTREME CAUTION WHEN OPERATING ADJACENT BATTER EDGE

When stopping the roller: Park on even ground and lower any attachments to the ground. Shift the gear selector to park position and apply the parking brake. Turn off the ignition and remove the keys

#### TRANSPORT & MAINTENANCE

! ALWAYS SWITCH OFF ENGINE AND ENGAGE ARTICULATION LOCKING DEVICE PRIOR TO ANY MAINTENANCE OR TRANSPORTATION

! ALWAYS USE EXTREME CAUTION WHEN DRIVING ON AND OFF FLOAT, ALWAYS HAVE A SECOND PERSON TO GUIDE YOU

## REFUELLING

NEVER refuel unless the engine is stopped and ignition turned off

**NEVER** smoke during refueling

O	pei	rat	or	· Si	ar	าลใ	U	re:
_	рО.	•		_	9		•	

Name:	Date:	Signature: